

Safety Issue Type: Recalls

December 01 2021 NHTSA Campaign Number: 21C006000

Child Seat Canopy Support May Pose Choking Hazard

A detached piece of plastic can present a choking hazard to a child, increasing the risk of injury.

NHTSA Campaign Number 21C006000

Manufacturer Clek, Inc.

Components CHILD SEAT

Potential Number of Units Affected 5504

Summary

Clek, Inc. (Clek) is recalling certain Liing, model number LG19U1, and Liingo, model number LGO20U1, infant child seats manufactured before September 15, 2020. A small plastic portion of the child seat canopy support may break and detach from the seat.

Remedy

Clek will provide a replacement canopy support along with instructions on how to replace it, free of charge. Owner notification letters are expected to be mailed in January 2022. Owners may contact Clek customer service at 1-866-656-2462.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (2)

Child Seat

CLEK	LIING	9999
CLEK	LIINGO	9999

Associated Documents (7)

Recall 573 Report

RCLRPT-21C006-6876.PDF 217.463KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C006-6876.PDF>

Recall 573 Report - Amendment 5

RCLRPT-21C006-5439.PDF 217.505KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C006-5439.PDF>

Recall 573 Report - 12/10/21

RCLRPT-21C006-5053.PDF 217.502KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C006-5053.PDF>

Remedy Instructions and TSB

RCRIT-21C006-1231.pdf 431.271KB

<https://static.nhtsa.gov/odi/rcl/2021/RCRIT-21C006-1231.pdf>

NHTSA Recall Cover Letter with Remedy

RMISC-21C006-0420.pdf 101.446KB

<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21C006-0420.pdf>

Recall Acknowledgement

RCAK-21C006-1945.pdf 693.235KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21C006-1945.pdf>

NHTSA recall notice on website - Canopy Issue

RMISC-21C006-0040.pdf 239.648KB

<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21C006-0040.pdf>